

Article 9 Commodity Inspection Mark:

1. The obligatory applicant for inspection shall demonstrate the commodity inspection mark on the body of goods, by the package of smallest unit or by hanging it out.
2. The obligatory applicant for random inspection of premises sampling shall print the commodity inspection mark by themselves. The other obligatory applicant can use the commodity inspection mark printed by BSMI or by themselves.
3. The identification number for the commodity inspection mark printed by the production factory acquires the management system monitoring inspection is “Q” and designated code. The identification number for the rest of the self-printed commodity inspection mark is “M” and designated code. The designated code is the registration number of monitoring inspection.
4. The obligatory applicant who prints the commodity inspection mark by themselves shall demonstrate the alphabet “M” or “Q” and registration number of monitoring inspection close to the right or underside of the commodity safety mark and present them both in the positions of upside and underside side by side. The obligatory applicant shall obey the following regulations to record or fill out the information and may label the batch number to implement the market management system and commodity traceability.
  - (1) The obligatory applicant for random inspection of premises sampling shall record and keep the product information about manufacturing date, quantity, production date, etc. by themselves and accept the inspection authority for document inspection.
  - (2) The domestic production factory acquires the management system monitoring inspection shall fill out the commodity inspection mark, QXXXXX, in the column of the proved commodity inspection mark signed and issued by themselves. ( XXXXX represents the registration number of monitoring inspection.)
  - (3) The obligatory applicant except the two items mentioned above shall report fully and accurately the self-printed commodity inspection mark MXXXXX

or QXXXXX in the column of commodity inspection mark on the inspection application.

5. The pictures of self-printed commodity inspection mark includes as following:

(1) The production factory acquires the management system monitoring inspection:



QXXXXX

or



QXXXXX

(2) Others:



MXXXXX

or



MXXXXX