

9. Commodity Inspection Mark:

- (1) An applicant is permitted to print the Commodity Inspection Mark, which consists of a diagram and an identification number (including two-dimensional barcode) and QR Code, on its own. The identification number shall be placed below or to the right of the diagram.

Example:



- (2) An application for the designated code mentioned in the preceding paragraph can be made to the BSMI or BSMI branches (hereinafter referred to as the inspection authority) in person, or through the BSMI Operation System for Declaration of Conformity.
- (3) The QR code is generated automatically by the system when the applicant enters the specified code (excluding the two-dimensional barcode) and selects the product category in the QR code application system of this Bureau.