

6. The inspection scheme of declaration of conformity:
  - (1) Type classification of low risk of hazard commodities listed in Appendix 1, Classified by commodities' material is as bellow:
    - a. Paper.
    - b. Plastic.
    - c. Other composite materials: Commodity contains more than 2 materials.
  - (2) The procedures to apply for type test report and test principles:
    - a. The procedures to apply for type test report: the inspection obligatory applicant submit the Table of Declaration of Conformity Type Classification (Appendix 7) to the designated testing laboratory for the application of type test report.
    - b. Test principles:
      - (a) Numbers of samples: The inspection obligatory applicant shall submit at least 3 samples.
      - (b) The testing items for the type test: The designated testing laboratory conduct the testing items for the type classification of commodities in accordance with Appendix 8.
      - (c) Choose of samples: The designated testing laboratory samples one of the most complexity samples for each type classification of commodities from the List of Declaration of Conformity Type Classification. If the items of type classification of commodities are accumulated less than or equal to 100, every 20 items to be selected one sample to conduct testing; If the items of type classification of commodities are accumulated more than one hundred, every 50 items to be selected one sample to conduct testing.
  - (3) The inspection obligatory applicant shall keep the declaration of conformity and relevant technical documents in accordance with the Commodity Inspection Act Article 46:
    - a. Declaration of conformity (Appendix 9).
    - b. Technical documents:
      - (a) Type test report issued by designated testing laboratory.
      - (b) Table of Declaration of Conformity Type Classification signed by designated testing laboratory (Appendix 7).
  - (4) Under any of the following circumstances of the signed the declaration of conformity and relevant technical documents of type test report and Appendix 7, the inspection obligatory applicant shall submit the original and modified Appendix 7, as well as original and modified type test report or samples to designated testing laboratory for the application. The test principles are as below:
    - a. For increasing the model or items in the List of Declaration of Conformity Type Classification Declaration:
      - (a) The accumulation items of type classification of commodities are over or equal to Article 6, Subparagraph 2, Item (2) of c. requirements that shall be conducted in accordance with Subparagraph 2 item 2.
      - (b) The accumulation items of type classification of commodities are not over Article 6, Subparagraph 2, Item (2) of c. requirements that shall be modified Appendix 7.
    - b. For modifying testing items for the type test, the designated testing laboratory conducts testing for modifying testing items.
  - (5) Commodity inspection mark: The inspection obligatory applicant shall apply to the inspection authority for commodity inspection mark, D and specified codes

(specified by the BMSI as issuing the notice); The commodity inspection mark D00000 self-printed by the inspection obligatory applicant, and shall be labeled on the body of the commodity concerned or the minimal package thereof and close to the right side or the underneath of the basic pattern.



D00000

or



D00000

(6)Registration fee: Fee in accordance with Regulations Governing Fees for Commodity Inspection.