

Annex

Coding Principles for Application No. and Report Number

Application No. and Report No.	Meaning	Description
1st & 2nd digits	Code of the factory inspection	FI: factory inspection for short
3rd & 4th digits	Code of the Inspection Authority	10: Hualien Branch 20: Keelung Branch 30: the BSMI 40: Hsinchu Branch 50: Taichung Branch 60: Tainan Branch 70: Kaohsiung Branch Factory inspection body: 7th & 8th digits of the body certification number (e.g., 02 from FIB41202 (Taiwan Electric Research & Testing Center))
5th & 6th digits	Code of the area where the factory is located	10: Hualien 20: Keelung 30: Taipei 40: Hsinchu 50: Taichung 60: Tainan 70: Kaohsiung Overseas: abbreviation of the country code in English (e.g., JP for Japan)
7th ~ 9th digits	Application serial number	From 001 to 999
10th & 11th digits	Last two digits of the	E.g., 21 from 2021

	year	
12th digit	Serial number	Report serial number of the year, starting from 1